DUST &WATER PROTECTION



1090

TEST REPORT

Application No.:SC0191082(E)



METAL INDUSTRIES RESEARCH & DEVELOPMENT CENTRE
INTELLIGENCE AND SYSTEM R&D SERVICE DEPARTMENT
NO. 25, 37TH ROAD, INDUSTRIAL PARK, TAICHUNG, TAIWAN, R.O.C.



INTELLIGENCE AND SYSTEM R&D SERVICE DEPARTMENT

NO. 25, 37TH ROAD INDUSTRIAL PARK, 407 TAICHUNG, TAIWAN, R.O.C.

TEL: +886-4-23502169

FAX: +886-4-23594799

DUST & WATER PROTECTION TEST REPORT

Page 1 of 4

Application No.: SC0191082(E)

Received date: Dec. 26, 2019

Applicant: AQUATEK.,LTD.

Address: NO.66, TUCHENG RD., DALI DIST., TAICHUNG CITY 41724, TAIWAN (R.O.C.)

Sampler: AQUATEK.,LTD.

Job description: IP67 dust and water protection test

Sample name: BC TAP

Test date: Dec. 30, 2019~ Dec. 31, 2019

Test place: Metal Industries Research & Development Center

No. 25, 37th road, Industrial park, Taichung, R.O.C.

Date issued: Feb. 20, 2020

Note: (1). This report is responsible for designated samples only.

(2). Reproduction of all or parts of this report without a written approval is strictly prohibited.

Report Authorized Person:

Chen-Ping Ho

Inspector:

Wei-Sen Chen



INTELLIGENCE AND SYSTEM R&D SERVICE DEPARTMENT

NO. 25, 37TH ROAD INDUSTRIAL PARK, 407 TAICHUNG, TAIWAN, R.O.C.

TEL: +886-4-23502169

FAX: +886-4-23594799

DUST & WATER PROTECTION TEST REPORT

Page 2 of 4

1 · Test according to:

IEC 60529:2013

Degrees of protection provided by enclosures (IP Code)

- 2 · Test equipment:
 - (1) Dust Protection Test Equipment
 - (2) Water Protection Test Equipment
- 3 · Test items & contents:
 - (1) IP6X Test: The DUT was put in a dust chamber, and its enclosure was connected to vacuum pump with underpressure continuous for 2 hours.
 - (2) IPX7 Test: The EUT was immersed 1000 millimeters under the water for 30 minutes.
- 4 · Results:
 - (1) IP6X test: Pass
 - (2) IPX7 test: Pass

Note: (1). This report is responsible for designated samples only.

(2). Reproduction of all or parts of this report without a written approval is strictly prohibited.



INTELLIGENCE AND SYSTEM R&D SERVICE DEPARTMENT


NO. 25, 37TH ROAD INDUSTRIAL PARK, 407 TAICHUNG, TAIWAN, R.O.C.

TEL: +886-4-23502169

FAX: +886-4-23594799

DUST & WATER PROTECTION TEST REPORT

Page 3 of 4



Front view of BC TAP

Note: (1). This report is responsible for designated samples only.

(2). Reproduction of all or parts of this report without a written approval is strictly prohibited.



INTELLIGENCE AND SYSTEM R&D SERVICE DEPARTMENT

NO. 25, 37TH ROAD INDUSTRIAL PARK, 407 TAICHUNG, TAIWAN, R.O.C.

TEL: +886-4-23502169

FAX: +886-4-23594799

DUST & WATER PROTECTION TEST REPORT

Page 4 of 4



Inside view of BC TAP

Note: (1). This report is responsible for designated samples only.

(2). Reproduction of all or parts of this report without a written approval is strictly prohibited.